

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Tillamook County Courthouse
201 Laurel Avenue
Tillamook
Tillamook County
Oregon

HABS No. OR-158

Morris W. Grover, Photographer

January, 1992

- OR-158-1 VIEW OF EAST WALL IN SOUTH LOBBY SHOWING MURAL AND
CIRCUIT COURTROOM ENTRANCE.
- OR-158-2 VIEW OF WEST WALL SHOWING MAIN ENTRANCE INTO SOUTH
LOBBY AND ALUMINUM VESTIBULE ADDED IN RECENT YEARS.
ELEVATOR WILL BE CONSTRUCTED TO THE RIGHT OF THE
DOORWAY IN THE NORTHWEST CORNER OF THE LOBBY.
- OR-158-3 VIEW OF THE NORTHWEST CORNER OF SOUTH LOBBY SHOT
FROM THE SOUTHEAST CORNER.
- OR-158-4 VIEW OF THE NORTHWEST CORNER OF SOUTH LOBBY SHOT
FROM THE NORTHEAST CORNER.
- OR-158-5 VIEW OF THE NORTHWEST CORNER OF SOUTH LOBBY SHOWING
THE AREA TO BE OCCUPIED BY THE HOISTWAY.
- OR-158-6 VIEW OF THE NORTH WALL OF THE SOUTH LOBBY SHOWING
THE DOORWAY INTO THE MAIN CORRIDOR.
- OR-158-7 VIEW OF THE NORTHEAST CORNER OF THE SOUTH LOBBY.
- OR-158-8 VIEW OF THE WEST WALL IN THE NORTHWEST CORNER OF
SOUTH LOBBY SHOWING THE TWO VENTILATORS TO BE
DISPLACED BY THE ELEVATOR HOISTWAY.
- OR-158-9 VIEW OF THE UPPER VENTILATOR TO BE DISPLACED.
- OR-158-10 VIEW OF THE LIMESTONE WAINSCOT AND MOULDING IN THE
NORTHWEST CORNER OF THE SOUTH LOBBY.
- OR-158-11 VIEW OF THE FOSSILIFEROUS (OOLITIC) LIMESTONE
WAINSCOT IN THE NORTHWEST CORNER OF THE SOUTH
LOBBY.